


# Well Pump Flange Leak Mitigation

OPNZ “Flange Seal” Repair System Can Reduce / Eliminate Pit Fluid Recirculation and save > 30% In Pump Energy Costs



**Typical Flange Appearance After Coating Applied**

# Typical Flange Appearance Before Coating Applied



# Typical Flange Appearance Before Coating Applied



# Typical Flange Appearance Before Coating Applied



# Typical Flange Appearance Before Coating Applied



# Typical Flange Appearance Before Coating Applied



# Typical Flange Appearance Before Coating Applied

